Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: 14014SO3699Work Order Type: WeatherizationAudit Name: 14014SO3699

CLIENT INFORMATION

Client Name: Address:

Client ID: 14014SO3699 SHELBYVILLE, TN 37160

Alt. Client ID: BEDFORD

<u>AGENCY INFORMATION</u>

Agency: South Central Human Resource Agency Agency Phone: (931) 433-7182

Address: (PO Box 638) 1437 Winchester Highway **Fax:** (931) 433-0074

Fayetteville, TN 37334 *Email Address:*

Agency Contact: MOOREHEAD, JIMMY Work Phone:

Cell Phone: Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Client Name:
Client ID: 14014SO3699
Alt. Client ID: BEDFORD

Work Order (Bid Form)
Work Order Name: 14014SO3699

Report Run On: 10/6/2011

DOE Weatherization Assistant Version 8.6.0 Page 1 of 6

Measures

	Measure 1 Inf	filtration Redctn			Componen	ts		1	Inspected
C	SEAL REGIS	IT DOOR DUCT WOR D RETURN RE HIGH ON							
#	Material / Labor	Description / Comment	Units	Qty	Estimated Unit Cost	Total	Qty	Actual Unit Cost	Total
1	Miscellaneous S	•	Each	1					
2	Labor	LABOR	Each						
C	Other Detail						¬		
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

Report Run On: 10/6/2011

	Measure 2 L	ighting Retrofits			Componen	ts LT1,L	T1 (2)		Inspected
C	omment								
					Estimated	<u> </u>			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Lighting	Compact FI 26 Watt	Each Lamp	1					
2	Labor	Compact Fl 26 Watt	Each Lamp	1					
3	Lighting	Compact Fl 26 Watt	Each Lamp	1					
4	Labor	Compact Fl 26 Watt	Each Lamp	1					
C	Other Detail								
				Measu	e Sub Total:] ;	Sub Total:	
Г	Field Notes:								
		WH Pipe Insulation ALL POP OFF PIPE insulat	e 3 ft hot	and c	Componen	ts			Inspected
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1					
		As per 2.4.1 of SWFG (page 2-11).						1	
2	Labor	DHW Pipe Insulation	Each	1					
(Other Detail						, ,		,
Ĭ	other Betan								
				Measur	re Sub Total:			Sub Total:	
	Field Notes:								

Client Name: Client ID: 14014SO3699 Alt. Client ID: BEDFORD

Report Run On: 10/6/2011

DOE Weatherization Assistant Version 8.6.0 Page 3 of 6

Measure 4	Floor Ins. R-19			Componen	ts F1			Inspected
Comment INS	TALL R 19 FLOOR INSULAT	TION SEA	L BAN	JOIST WIT	H 2 PAR	T FOAI	M	
				Estimated	<u> </u>		Actual	
# Material / Labo	r Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	1104					
2 Labor	Floor Insulation - Fiberglass Batts - R-19	SqFt	1104					
Other Detail								
			Measure	e Sub Total:			Sub Total:	
Field Notes:								
Manager 5				Componen	40 A1			Inspected
Comment INS	Attic Ins. R-30 FALL R 30 ATTIC INSULATION RFOAM BOX OVER PULLD				UILD			Inspected
Comment INST	TALL R 30 ATTIC INSULATION RFOAM BOX OVER PULLD		FLES 4	FLAGS B	UILD		Actual	
Comment INS	TALL R 30 ATTIC INSULATION RFOAM BOX OVER PULLD	OWN <i>Units</i>	Qty	FLAGS B	UILD	Qty		Inspected Total
Comment INST	TALL R 30 ATTIC INSULATION RFOAM BOX OVER PULLD	OWN	FLES 4	FLAGS B	UILD	Qty	Actual	
Comment INST STY	FALL R 30 ATTIC INSULATION FROAM BOX OVER PULLD The description of the comment o	OWN <i>Units</i>	Qty	FLAGS B	UILD	Qty	Actual	
Comment INST STY # Material / Labo 1 Insulation	TALL R 30 ATTIC INSULATION REPORT BOX OVER PULLD The description of the comment	OWN Units SqFt	Qty 1104	FLAGS B	UILD	Qty	Actual	
# Material / Labor 1 Insulation	TALL R 30 ATTIC INSULATION REPORT BOX OVER PULLD The description of the comment	OWN Units SqFt	Qty 1104	FLAGS B	UILD	Qty	Actual	
# Material / Labor 1 Insulation	TALL R 30 ATTIC INSULATION REPORT BOX OVER PULLD The description of the comment	OWN Units SqFt	Qty 1104	FLAGS B	UILD	Qty	Actual	
# Material / Labor 1 Insulation	TALL R 30 ATTIC INSULATION REPORT BOX OVER PULLD The description of the comment	OWN Units SqFt	Qty 1104 1104	FLAGS B	UILD		Actual	
# Material / Labor 1 Insulation	TALL R 30 ATTIC INSULATION REPORT BOX OVER PULLD The description of the comment	OWN Units SqFt	Qty 1104 1104	Estimated Unit Cost	UILD		Actual Unit Cost	
# Material / Labor 1 Insulation 2 Labor Other Detail	TALL R 30 ATTIC INSULATION REPORT BOX OVER PULLD The description of the comment	OWN Units SqFt	Qty 1104 1104	Estimated Unit Cost	UILD		Actual Unit Cost	
Comment INSTATE STY # Material / Labo Insulation Labor Other Detail	TALL R 30 ATTIC INSULATION REPORT BOX OVER PULLD The description of the comment	OWN Units SqFt	Qty 1104 1104	Estimated Unit Cost	UILD		Actual Unit Cost	

Report Run On: 10/6/2011

ı	Measure 6 Fix I	mproper Venting (Cloth	es Dryer)	Componen	its			Inspected
C	comment Vent to e	exterior and cap as per 2	2.5.4 of S\	NFG (p	ages 2-17 a	•).	Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Exterior Cap / Metal Flex / Clamps	Each	1					
2	Labor	Labor	Hour	3					
C	Other Detail						1		
L							1		
				Mossur	e Sub Total:] []	Sub Total:	
Г	Field Notes:			Weasur	e Sub Total.		`	oub rotur.	
					_	_			
	omment INSTALI	ke CARBONDetector is L SMOKE CARBON DET			Componen Estimateo				Inspected
С	Material / Labor	L SMOKE CARBON DET			Componen Estimated Unit Cost		Qty	Actual Unit Cost	Inspected
C #	Material / Labor		ΓECTOR	Qty 1	Estimated	<u> </u>	Qty	Actual	
C # 1	Material / Labor	L SMOKE CARBON DET	TECTOR Units	Qty	Estimated	<u> </u>	Qty	Actual	
C # 1	Material / Labor Health and Safety	L SMOKE CARBON DET Description / Comment Smoke carbon detector	Units Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
C # 1	Material / Labor Health and Safety Labor	L SMOKE CARBON DET Description / Comment Smoke carbon detector	Units Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
C # 1	Material / Labor Health and Safety Labor	L SMOKE CARBON DET Description / Comment Smoke carbon detector	Units Each	Qty 1 1	Estimated	<u> </u>		Actual	
c # 1	Material / Labor Health and Safety Labor	L SMOKE CARBON DET Description / Comment Smoke carbon detector	Units Each	Qty 1 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	

Report Run On: 10/6/2011

DOE Weatherization Assistant Version 8.6.0 Page 5 of 6

•	•	ement/Crawlspace)			Componen	13			<u></u>
C		mil poly as ground cover on walls and piers 6" and	•				p up		
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Basement / crawlspace vapor barrier	SqFt	1					
2	Labor	Labor	SqFt	1					
C	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								
			Work Or	der Gra	and Total:		Gran	d Total:	

Report Run On: 10/6/2011